



Insert the legs into the aluminum leg caps so that they are properly oriented and the buttons snap into place. To remove legs depress the snap buttons with a pen and pull the legs out of the leg caps.



The assembled legs and cross member should look like this with the skirt attachment bolts toward the front.



Attach the black plastic skirt to the frame with the thumb nuts and washers provided.



Slide the 3rd hand onto the back of the frame. The 3rd hand holds the gold pan that will collect the values that come through the center of the pan.



Attach the motor / switch plate to the cross member using the bolts and washers provided. After the plate is mounted place the fan belt over the pulley so that the belt will be in place when you insert the wheel.



Insert the wheel into the brass bushing making sure the fan belt is in place. Adjust the tension on the fan belt and tighten the motor plate bolts. Screw the spray bar onto the water valve and attach the 5/8 clear hose from the pump to the water valve.

Your Gold Genie Miner Model is now fully assembled and ready to go to work separating gold and other values from the waste material.

